

18 NOV 1958

P'S NAME "BALLYHENRY" REPORT Bel. No. 16546.
AR.

standing Conditions of Class: Subject to rudderstock (twisted 15° to port) being specially examined at next drydocking.

Amendment of Certificate (As before ~~on line~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking; W & T repairs.

Recommendation: SUBMITTED record of 'DS 10,58' be assigned as recommended SUBJECT to rudder stock and main piece (E.W.10,58) being specially examined next drydocking.

DS 10,58. Subject.


C.S.S. Records Dept.
to note.

S.R.L. APPENDIX. (Amended).

Stem and stern plating buckled.

Rudder plate bent.

Shell plating (p.s.f) indented
(Rudder stock twisted 15° 11.56).



© 2020

Lloyd's Register
Foundation

James
13/11/58