

*W. F. Bolbee X.*

Chief Surveyors *31. 10 18*

Received from Chief Surveyors

S NAME

*Shells Ardguvian*

Report

*Lib.*

No. *17374*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

When due

*The Hand pumps have been dispensed with for the present.*


*2. 100 A-1 (Steel)*

*1 1/2" (Steel) Well OK*

*Cell 5B 190. 3956 A.P.T. 556*

*FK. 4 BH. Com. Separated 279' B. 48' F. 28'*

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book.



© 2020

Lloyd's Register  
Foundation

002515-002521-0078

Height of Outside Brackets above at bridge  
INNER BOTTOM PLATING, breadth and

34

40

34

40

Wood Deck, Material & thickness