

Rpt. 8

Port. CARDIFF.

No. 61710

Date of writing Report 27th April, 1962.

When handed in at Local Office 27 APR 1962

Received London

Survey held at Cardiff.

No. of Visits 1

First Date and 19

Last Date 4. 4. 1962.

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

05082

on the ~~Iron~~ Steel M.S.

"BRITISH VIRTUE"

Tons gross 8553

Year 1945 Month 6

Built at Newcastle.

By Whom Swan, Hunter & Wghm Rchdsn

When 1945 6

Owners The British Iron & Steel Corporation.

Owners' address (If not already in R.B.)

Managers

Port of Registry London

Surveyed Afloat or in Drydock Afloat

Name of Dock Queen Alexandra Dock.

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 61482

Port

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
CLASS EXPUNGED. TO BE BROKEN UP.	

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined to Owners.

Freeboard as marked on ship and now verified - ft - ins

but not required.

Was a damage report made by anyone else? If so, by whom?

No

EXAMINATION AND REPAIRS AS PER RULE FOR Condition.

Attended vessel at the request of The British Iron & Steel Corporation for the purpose of examining the hull prior to vessel being towed from Cardiff to Troon as a hulk for breaking up, the towing arrangements being the responsibility of the Owners, and the vessel unclassified for duration of voyage.

Now Done:- Weather decks, superstructures and casings; hatchways, tank coamings, covers, ventilators, air pipes, skylights, companionways and all closing and securing appliances examined, tightness of tanks and bilges verified from sounding records, and hull considered in fit condition for the intended voyage.

Damage stated caused by contact with quay on 3rd March, 1962 at Cardiff, examined and found side shell plates in 2nd and 3rd strakes below sheer indented in way of No. 1 Cargo Tank, port side. Butt of shell plates in 3rd strake below fractured approximately 18 inches covered by a resin bonded patch. Side frames Nos. 2, 3, 4 from aft end of tank port side found buckled.

The plating and framing remain efficient and are considered in fit condition for the intended voyage.

CONTINUATION OVER/ON REVERSE

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? No

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent?

Has Interim Certificate been issued? Rpt. 10 issued, copy attached.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

For the information of the Committee only.

James D. J. Key
Surveyor to Lloyd's Register of Shipping

THURSDAY 10 MAY 1962

Date of Committee

Minute

Moted
(See late minute dated 4/7/61)

Noted for Header



© 2020

Lloyd's Register Foundation

002515-002521-0165

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR SURVEY

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock			F.P. Tank		
Rudder lifted			A.P. "		
Weather Decks, Superstructures and Casings			D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances					
Ventilator coamings, skylights, companionways and closing appliances			Fresh Water Tanks		
Holds			Deep Tanks		
'Tween Decks			Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces			Side Tanks		
After " "			Wing Tanks		
Engine Space			Other Tanks		
Boiler "			Cargo Tanks (Tankers)		
Under Engines and Boilers					
Tunnel and Well			Cofferdams		
Coal Bunkers			Pump Rooms		
Chain Locker					
Other Spaces					

Condition as stated overleaf

Have Tanks now Examined been Cleaned as Necessary?

Have Struts in Cargo Tanks (of Tankers) been removed?

Have Tanks been Retested as necessary after completion of any Repairs?

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held?

If so, state which

Have the shell and deck plating been drilled as per Rule?

If so, Report 8(Dr) to be attached

Have any alterations to the approved scantlings and arrangements now been effected?

If so, report details in body of Report

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes, or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes
Decks	Hatches and closing appliances	Masts and Rigging examined and found
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)
Coamings and Casings	Companionways and Skylights	Chain Locker
Beams and Fastenings	Shell Openings	EQUIPMENT
Frames	Ash Shoots	Equipment Letter
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)
Transverses	Steering Gear (Main and Auxiliary) examined and found	" length mean diam. (on board)
Floors	Windlass examined and found	" Rule Length Size
Keelsons	Pumps " " "	Hawsers and Warps
Stringers	W.T. Doors " " "	State if any Anchors or Chain Cable have now been supplied or retested, if so
Inner Bottom Plating		complete Report 8(Eq) and attach.
Bulkheads and Tunnel		

Have conditions (A) or endorsements (B) of Class (if any) been dealt with?

See Below

REMARKS, REPAIRS, Etc. (Contd.)

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Survey Fee Condition £15.15.0

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Date when A/c. Rendered

