

Bonaire

Ceo 2182.

Submitted the Ceo. Surveyor he informed that if the information given in his report & his Ltr dated 8/12/42 is correct, some of the electric cables are grossly overloaded & many of them reported as single wire cables are of a size requiring stranded cables.

The main dynamo cables for instance carry 455 amperes but by rule are good for 1350 amps only & the Emergency Bridge pump motor which is reported requires so much as 350 amps has a cable good for 50 amps only. Several other cables are similarly deficient if the report is correct. In the circumstances the Surveyor should arrange to again examine the installation & make good the deficiencies if any.

CB 11/5/43. RJA 3/3/43.

For  
at c