

"BRITISH ENSIGN" - Lth. Rpt No.24993

The class is subject to indented shell plates F.13, G.13 and J.13 (p.s.) also J.3 & H.3 (s.s.) being permanently repaired next Special Survey and to indented shell plate in 2nd below sheer immediately forward of after cofferdam (s.s.) being dealt with at the next drydocking.

There is a S.R.L.Appendix Note.

The ship is laid up and the Notation "Laid Up Surveys Overdue 7,59" was assigned 8,60 on expiry of the year of grace (7,60).

The LEITH Surveyors in a report dated 12.7.61 state that a General Examination has been held with a view to towing the ship to a Firth of Forth port from Methil for breaking up.

The case has been transmitted to London.

IT IS SUBMITTED ACTION be DEFERRED pending receipt of further information.

IN S.R.L. APPENDIX.
Indented shell plate G.3 (p.s.f).



© 2020

James
11/8/61
Lloyd's Register
Foundation

007559-002567-0004