

Rpt. 8

Port LONDON

No. 140070

Date of writing Report 9.4.59

When handed in at Local Office 10.4.59

Received London 24 APR 1959

Survey held at Greenhithe

No. of Visits 1

First Date 8.4.19 59

Last Date 8.4.19 59

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B.

61439

on the Iron or Steel M.S.

"FRIVOLITY"

Tons gross 410

Built at Goole

By Whom Goole S.B. & R. Co. Ltd.

Year 1944 Month 8

Owners F.T. Everard & Sons Ltd.

Owners' address (If not already in R.B.)

Managers

Port of Registry London

Surveyed Afloat or in Drydock On slipway

Name of Dock Greenhithe

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 159312

Port LOW

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery	
BS* for service in the Baltic & Mediterranean & European coasting including Gt. Britain & Ireland but not north of 60°N.	MBS* CS.	11-55
	TS. OG.	12-57
	Oil Eng.	
S.S. Lon.		12-57
		11-55

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified ft. ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR DOCKING.

NOW DONE:- All Rule requirements of docking survey carried out.

WEAR & TEAR REPAIRS:- Rudder the upper and lower bushes renewed at this time.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent? Now

Has Interim Certificate been issued? Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This ship as now seen is eligible in my opinion to remain as classed with fresh record of docking 4-59, subject to all outstanding conditions of class being dealt with as previously recommended.

K.C. Kirby
Surveyor to Lloyd's Register of Shipping
K.C. KIRBY

Date of Committee

THURSDAY 30 APR 1959

Minute

DS 4, 59, subject

Noted for Header



© 2020

Lloyd's Register

Foundation

002583-002591 0121

