

REPORT OF SURVEY FOR REPAIRS, &c.

Writing Report... 6/6/1957. When handed in at Local Office... 1957. Port of GRIMSBY.
Survey held at IMMINGHAM. Date, First Survey 23/5/57 Last Survey 5/6/1957.
(No. of Visits... 3...)

on the ~~Wood, known as~~ Steel S/S. "FULHAM III"
Built at Burntisland By whom Burntisland S.B.Co.Ld. When 1937 4
Tonnage: 1596 Owners Central Electricity Authority. Owners' Address
ER DK. 875 Managers Stephenson Clarke, Ld. Port belonging to London.
(It not already recorded in Appendix to Register Book).

oyed Afloat or in Dry Dock? Both. Name of Dock Humber Gray Dk & King's Dock. Destined Voyage -
Bor DBa feet; uE & B feet; f feet; fe }
capacity tons. FPT tons; APT tons; MT tons. }
Only alterations in the existing records of tanks should be inserted.

V.B. All alterations in the existing records should be underlined.

st Report, No. 36689 Port SLD

ical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and Items remaining to complete
Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations
subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to
er causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
lacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.
te also the dates and initials of any letters respecting this case.

mage cases where the Surveyor has not made a special damage report he is required to state whether he
offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)	
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
+100A1 with freeboard 6,56.	+LMC 7,54. BS 6,56. TS.OG. 7,54.
s.s.Pen.- 7,54.	

Society's Freeboard (if assigned) as } 6 ft. 3 1/4 ins.
painted on Ship and now verified }

Was a damage report made by anyone else? if so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR DOCKING & ANNUAL LOAD LINE SURVEY.

V DONE: Vessel placed in drydock. Bottom, rudder and sternframe cleaned and examined,
found or placed in good condition and recoated. Last seen in drydock 23/5/57.
Decks, hatches, casings, coamings, ventilators, closing appliances, steering gear,
windlass and general equipment generally examined and found in good condition.

Sundry minor wear and tear repairs effected.

ual Load Line Survey held at this time, please see separate Rpt.C11(a). Freeboard marks
verified and found correct.

(Contd. over)

ARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...	-	-	-	-	-	-	-	-
Removed and Faird or Repaired	-	-	-	-	-	-	-	-
Faird or Repaired in place ...	-	-	-	-	-	-	-	-

NT CONDITION OF THE Parts now surveyed:—	
Good.	Bulkheads
Good.	Ceiling
Good.	Cement or Asphalt
-	Rudder
Good.	Steering gear and its connections
-	Windlass
-	Have pumps been examined and found effi- cient? Not exd.
-	Have Sluice Valves been examined and found efficient? -
-	Have Watertight Doors been examined and found efficient? Not exd.
-	Have Ventilators and their Coamings been examined and found efficient? Yes.
No.	Air and Sounding Pipes On deck good.
No.	Doubling Plates under Sounding Pipes

Engine Room Skylights	Good.
Coal Bunkers, Openings, Covers, &c.	Good.
Oil Bunkers	-
Scuppers	Good.
Cargo Hatchways	Good.
Hatches	Good.
Planking	-
Caulking	-
Treenails	-
Breasthooks & Stemson	-
Transoms, Pointers & Crutches	-
Timbers of Frame at openings	-
" " at other places	-
Stringers, Clamps & Shelves	-
Salting	-
State if examined	

Copper, or Y.M.	-
(State if on Felt.)	-
When fitted, Month	Year
Boats	-
Masts, Yards, &c.	Good.
Condition, how ascertained	From deck.
(State if wedges removed.)	
Equipment letter	
Anchors, No. of	3B, 1S.
Cables (State if now ranged)	Not.
" length mean diamr.	stated complete.
" (on board.)	
" Rule length size	
Chain Locker	-
Hawsers & Warps	Good.
Standing and Running Rigging	-
Sails	Good.

eneral Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38."

This vessel is eligible, in my opinion, to remain as classed with fresh record of Docking
Survey 5,57.

vey Fee (per Section 23)	£	:	:	Fees applied for,
cial Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19.
elling Expenses (if chargeable)	£	:	:	Received by me,
nd Surveyor's Fee (if any)	£	:	:	19.

mmittee's Minute

TUESDAY - 9 JUN 1957

aracter Assigned

DB. 5.57 MBS 6.57
DBS 6.57
TS 5.57

William SEDH
Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation
002620-002630-0075

ALTERATIONS:- All four ventilators to the holds have now been fitted with 5/16" steel watertight covers and hook bolts as their closing appliances.

Rpt.C11 (Contd.) placed on board.

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side