

Chief Surveyors _____

Received from Chief Surveyors _____

L'S NAME Stl S " DALIA "

Report BTK No. 19304

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey 1st Entry When due _____ Revised Rules _____

✠ 100 A. I. (Steel). With Heebord.

2 D¹⁰ (Stl) + Shelter D¹⁰ (Stl)


Cell D.B. 351' 10675, D.T. a 35' 9075, A.P.T. 2235.

F.K. Intermediate Tween deck bulkhead in after hold dispensed with;

Collision bulkhead to Shelter D¹⁰, H.B.H. to second dk, 1 B.H. to 3rd D¹⁰

len, Lloyds A.C.P.

F 26'.



© 2020

Lloyd's Register Foundation

The Surveyors should be requested to forward the casting reports for the sternframe.

✓
on 13/3/31

002630-002638-0143