

Victory ship VC2 - S - AP2 Type

mw

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME s.s. "NIKOBAR" Bal. No. 8492
(ex Rushville Victory) REPORT

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER~~ SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Part S.S. for Classification, ~~Alterations~~ Alterations and Repairs.

This vessel was built in 1945 and classed with the American Bureau of Shipping.

Classification with this Society as well as with the American Bureau of Shipping is desired.

Plans of midship section and general arrangement for this type of vessel have been examined at this Office and the scantlings and arrangements found suitable for the class 100A-.

For further particulars see endorsement 9.5.46.

The BALTIMORE, Md. Surveyors, on a First Entry Report and Rpt. 8, report (4.47) the scantlings and arrangements verified and the requirements for Vessels Not Built Under Survey and of a Periodical Special Survey partly complied with.

A hinged watertight door is fitted for access to the shaft tunnel.

TO COMPLETE S.S.: - The vessel to be examined in dry dock, F.W. D.B. tanks under mchy space and peak tanks to be examined internally, all D.B. tanks, deep tanks, and peak tanks to be tested, anchors, cables and chain locker to be examined and equipment of anchors and chain cables to be verified with certificates. Tunnel watertight door to be altered to comply with the Rules.

This vessel was examined in dry dock by the American Bureau of Surveyors in March 1947.

100A1 (Classification Contemplated)
"Examined 4.47"

2 1/8"

Equipment letter for fus. "cf" in red.



S.S. FOR CLASSIF^N.
PART HELD
© 2020

Lloyd's Register
27.8.47
Foundation