


COPY

# LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE.

13th February, 1961.

This is to Certify that I have  
Surveyed the Machinery of the M.V. "DAPHNELLA" 8078 tons gross of  
LOND N whilst in drydock at Singapore on the 12th February, 1961  
and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel ~~the following~~  
~~Survey Records be made in the Supplement to the Register Book~~

~~and that~~ her Machinery Classification Record be continued in the Book,  
subject to the propeller (blade fractured) and the screwshaft  
outer end (rope around shaft) being specially examined and  
dealt with as found necessary before the ship is re-commissioned.

**Parts now examined:**  
(C.S. Items only)

*W. H. Taylor*

Engineer Surveyor to Lloyd's Register  
(W. H. TAYLOR).

## KEY TO ABBREVIATIONS

|     |  |        |                                   |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS    | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS    | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS     | Tailshaft Survey                  |
| ES  | Engine Special Survey                      | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN    | Tailshaft renewed                 |
| MES | Modified Survey of Oil Engines             | TS(OG) | Tailshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |        |                                   |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

002659-002666-0138

Lloyd's Register  
Foundation