

Empire Mandalay

Sld 34109

12 JAN 1945

Before this case receives consideration it is submitted
the Surveyors be requested to state whether the
varnish Cambrie insulated cables fitted on this
vessel have been sealed at the ends

The maximum current in the circuits
omitted from report should be forwarded.

Thus
11.1.45

See Sld letter
19.1.45



© 2021

Lloyd's Register

002682-002689-0157

Foundation

5c, 11, 38.

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Casno per

Rpt.

No.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Comm

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Oil Engine 250 D.A.
6cy. 23 5/8 - 43 5/16

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner



© 2021

Lloyd's Register Foundation

REGISTER

gth

width

th

FRAMES,

SIDE FR

Frame

Reverse

Depth

Frames