

Received from Chief Ship Surveyor 18 NOV 1960

SHIP'S NAME "DILOMA" REPORT BEL No. 16871

EA

Outstanding Conditions of Class: SUBJECT to indented side shell plating (p & s) being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix. (As before or None)

Nature of Present Survey: (Afloat and in dry dock)

Damage (grounding) involving D. ^{strake} ~~2~~ shell plating etc. in way of Nos. 2 & 3 cargo tanks (s.s)

Recommendation:

SUBJECT as above and to D. ^{strake} ~~2~~ shell plating and structure in way of Nos. 2 & 3 cargo tanks being permanently repaired next drydocking, but ACTION continue to be DEFERRED for examination in drydock after grounding.

SUBJECT.

IN S.R.L.
Drydocking (grounding). ✓



© 2021
14-11-60

Lloyd's Register
Foundation