

4E

ect to the grinding mark on the Starboard screw shaft core
in way of the rubber ring being specially examined
by 7/62 (12 mos limit)

12 DEC 1961

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME "AUGUSTENBURG"REPORT HAMNo. 11045

Docking
CSM advanced

Assign CSM 10/61
22/3/62
See reply to Mr
Walburn ltr

It is submitted that this
vessel is eligible to remain
as **CLASSED**.

Subject as above

22/3/62

The Surveyors to be advised that to complete the CSM
the N°1 and 2 cylinders, pistons, rods, valves and gears,
connecting rods, top ends and guides, crank pins and
bearings of the Port and Starboard main engines remain
to be examined.

They should issue an amended interim certificate
with correct date regarding the examination of the
subject item as recommended in their report N° 10676

© 2021

Lloyd's Register
Foundation

12/12/61

002690-002700-0284

rubber ring being specially examined by January, 1962, as previously reco