

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 58040 Survey held at on the Wood, Iron or Steel S.K. "HORTENSIA" Date, First Survey (No. of Visits) Last Survey 19

TONNAGE— Built at Dundee By whom Dundee S.B. Co Ltd. When 1907-7. GROSS 244 Owners W. Garratt Owners' Address (if not already recorded in Appendix to Register Book). Port belonging to Grimsby

UNDER DK 224 Managers

NET 118

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. Date of last Survey and of Periodical Surveys. Years Assigned to next Survey. Machinery and Boiler Surveys (including date of N.B. if any).

+ 100 A1 - 8.29 + LMC 10.25

Stm Flr. BS. 9.28

S. G. N° 3 - 10.25 TSCL 8.29

Last Report, No. 1666 y Port fms.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed ...								
Removed and Faird or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month
Decks	State if Tanks now tested	Engine Room Skylights	Boats
Caulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Coamings	Ceiling	Scuppers	Condition, how ascertained (State if wedges re)
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Outside Plating	Rudder	Hatches	Equipment letter
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Transoms	Windlass	Caulking ditto	Cables (State if now range)
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	" length (on board)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Floors		Ditto ditto at other places ditto	
Keelsons		Stringers, Clamps & Shelves ditto	
Stringers		Salting ditto (State if examined.)	
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	Received by me, 19
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute TUE, 22 JUL 1930 Withdraw class & insert 5.1.30 Write over to 24.7.30

© 2021 Surveyor to Lloyd's Register of Shipping. General Committee Thursday 24th July 1930 Lloyd's Register Classification Committee's decision confirmed