

I have to report that the Freeboard from the centre of disc to the top of the

Chief Surveyors

Received from Chief Surveyors

L'S NAME *Stet S. S. DAKARIAN*

Report *90*

No. *14501*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

of Survey

When due

Separate endorsement regarding date of build

✱ 100-A-1. (Steel) "Shelter Deck with freeboard"

2 Dks (Steel) + Shelter Dk (Steel)

Cell DB 340' 963t, DTf 24' 641t, DTa 26' 670t, FPT 123t, APT 30t.

FK 2 BK 2", 6BH to Shelter Dk 1BH to upper Dk, pt Cen, Klay as A + CP, B 143' on Shelter Dk.

Date of build 11.2.1.



© 2020

Lloyd's Register
Foundation

002711-002716-0115