


"CAPETAN MANOLIS"

PIR 9332.

Before this case receives consideration, the Surveyor should be requested to confirm that the heaters of the oil fuel installation also the oil fuel tanks not forming part of hull structure were examined and found satisfactory.

*(Filled)*



26.1.62.

© 2020

Lloyd's Register  
Foundation

002743-002749-0101