

required having been filled in by the Surveyor.

00,11,28.

EBOARD REPORT on the

Mr. "Thurland Castle"

This submitted the Liverpool office he informed that it is observed that the length on load waterline is given as 450 feet. It is assumed that this is an error and that the length should be 460 feet. They should forward an amended report giving correct dimensions and particulars, and they should be careful to see that the lengths of the sections correspond with the length on waterline.

They should give dimensions and full particulars of all the hatchways on both the upper and second decks.

M. S. LWB  
9.5.29

© 2021

Lloyd's Register  
Foundation

002762-002769-0161

Winter North Atlantic Line

If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.

+ State dimensions of freeing port area on back of this form.

+ The Surveyor should state whether the fall in sheer as reported is measured relatively to the straight line the vessel's draft at time of