



Lloyd's Register of Shipping,

Maritime Buildings, East Dock Street,

Dundee, *23rd June, 1916.*

Sir,

With reference to Dundee First Entry Report No. 7947, on the machinery of the steamer "DENPARK", and with regard to the water space stay ends in way of manhole openings at lower part of the back end plates of both main boilers I beg to advise you that, when under steam, leakage developed at these parts.

Steam stay nuts out of the turbine were removed and, after recaulking the plate, thicker, machined, washers with grommets were fitted with apparently satisfactory results.

This matter is under discussion between the Owners and Builders and may be brought up again before the guarantee period has expired.

I am, Sir,

Your obedient Servant,

*The Secretary,
London.*

James Lloyde

Lloyd's Register
Foundation

Referred to the Chief Engineer Surveyor.

RM
JUN 24 1916

JWA
26/6/16



© 2020

Lloyd's Register
Foundation