

بى شركة الن

4E
8 SEP 1960

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME EL GAMIL. REPORT ADN. No. 2939


Examined propeller for damage alleged to have been sustained due to propeller striking quay wall.

Four bladed cast iron propeller found with one blade with approximately 6" broken off one tip.

Main engine shafting in tunnel examined under working conditions and found to be satisfactory.

The damaged to the propeller is not considered too serious and the surveyor therefore recommends that the propeller be again examined and dealt with as found necessary at the next drydocking. Considered efficient meantime.

IT IS SUBMITTED that this vessel is eligible to remain as classed. Subject as now recommended.



6.9.60.

ادارة



© 2020

Lloyd's Register Foundation

002798-002807-0185