

How built in File; no gangways and no ladders to life line

Rosina Topic

Tri. 9814

# PARTICULARS OF PROTECTION TO OPENINGS, ETC.

HATCHWAYS ON FREEBOARD <del>AND SUPERSTRUCTURE DECK</del> <i>within Superstructures.</i>									
Description of Hatchway ... ..			<i>undropen to Fore Hatch</i>	<i>within Bridge Space to + Gunter</i>	<i>to Side Gunter Port + Starboard</i>				
Dimensions of Hatchway ... ..			3'8 1/2" x 3'11"	4'11" x 15'1 1/2"	4'7" x 3'0"	3'9" x 3'0"			
COAMINGS	Height above Deck ... ..	...	8 1/2"	16"	15"	15"			
	Thickness { Sides ... ..	...	Bulb angles	.36"	.30"	.30"			
	{ Ends ... ..	...	3 1/2" x 3 x 40	.36"	.30"	.30"			
	Stiffeners ... ..	...	"	"	"	"			
	Brackets, Stays ... ..	...	"	"	"	"			
HATCH BEAMS	Number ... ..	...	one	one	one	one			
	Spacing ... ..	...	at 1/2 length	at 1/2 length	at 1/2 length	at 1/2 length			
	Scantling and Sketch ... ..	...	none	B. A. 8 1/2 x 3 x 50	none	none			
	Bearing Surface ... ..	...		3"					
FORE AND AFTERS	Number ... ..	...	none	none	none	none			
	Spacing ... ..	...							
	Unsupported Lengths ... ..	...							
	Scantling* and Sketch ... ..	...	none	none	none	none			
	Bearing Surface ... ..	...							
HATCH COVERS	Material ... ..	...	White pine	White pine	White pine	White pine			
	Thickness ... ..	...	2 1/2"	2 3/4"	2 3/4"	2 3/4"			
	How fitted ... ..	...	fore aft	longitudinally	transversely	transversely			
	Bearing Surface ... ..	...	1 1/2"	2 1/2"	2 1/2"	2 1/2"			
Spacing of Cleats ... ..			29 1/2" x 32 1/2"	23 x 25	14 x 21 1/2	14 x 18"			
Number of Tarpaulins ... ..			2	1	No tarp.	No tarp.			

\*Are wood fore and afters steel shod at all bearing surfaces? ☒

Are battens and wedges efficient and in good condition? ☒

Are tarpaulins in good condition and in accordance with rule requirements? ☒

Are lashings provided in accordance with rule requirements? ☒

note \* wanted through in places  
Lloyd's Register Foundation