

ACTION is DEFERRED for examination in drydock
after grounding.

Received from Chief Surveyors.....

Chief Surveyors.....

"JAMES H. BEAZLEY"

REPORT.....

Liv.

No. 147567.

SHIP'S NAME.....

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

re of Survey..... Docking. Deferred repairs. When due

NOTED

ENDORSEMENT OF CERTIFICATE.

Stem bar set over, etc.
Shell plates in 1st below forecastle
sheer and upper deck sheer amidships
(p & s) indented. Shell plate No.4
in 1st below sheer (s.s.f.) indented.

DELETE FROM S.R.L.
Drydocking (grounding).

CPM.
26.9.51.



© 2020

Lloyd's Register
Foundation

002838-002845-0107