

Received from Chief Ship Surveyor 22 APR 1953

NAME DIMITRIOS A. KYDONIEFS REPORT Candift No. 58255

anding Conditions of Class:

Subject to N° 7 plate in 4" below sheer (s.s.)
(repairs Nov. 5-52) being specially examined next dry-docking, and to shell plate
F18 (s.s.), indented, being dealt with as necessary next Special Survey

sement of Class (B) (As before or None)

e of Present Survey: (Afloat and in dry dock)

Temporary repairs to damage caused by contact with quay wall
Conversion to O.F. burning, in accordance with approved plans

Recommendation: Subject as above, and to permanent repairs to indented shell
plating etc, in 1st strake below sheer, in way of A.P. bulkhead (s.s.), at
next dry-docking, by 9-53.

As now, subject

Insert in R.B.-

"Fitter for oil fuel 3-53. F.P. above 150°F"

Endorsement of Class (B)

Stem bar set over

Indented shell plating (pos)



© 2020

Lloyd's Register
Foundation

002846-002852-0221