

should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

S.S.B.As.(Dr.) 5.54

TS OG p. & s

sps 5.54

Received from Chief Ship Surveyor

9 AUG 1957

SHIP'S NAME "CIUDAD DE BUENOS AIRES" REPORT B.As. No. 28254.

Outstanding Conditions of Class: Subject to the starboard bower anchor being replaced by one of approved weight (42 cwt.) at the earliest opportunity.

Improvement of Class (B) (~~As above~~ None)

Future of Present Survey: (Afloat and in dry dock)

Docking.

Recommendation:

SUBMITTED notation of "DS 6,57" be assigned, SUBJECT as above.

DS 6,57. Subject.

31/7/57.

© 2021

002853-002857-0076

Blk(new)

This vessel, as far as now seen, is in good condition eligible in my opinion to remain as now classed Register Book, and to have fresh record of DOCKING SURVEY 6,57 and subject to starboard bower anchor replaced by one of approved weight (42 cwt.) at earliest opportunity.

Register Book copy record of drydock