

- 32 Essential Independent Pumps (Identify by position)
- 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
- 35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)
- 38 Independent Air Compressors, Coolers & Safety Devices
- 39 Air Receivers & Safety devices—Main 40 Auxiliary
- 41 Oil Fuel Tanks (Not forming part of hull structure)
- 42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?
- 44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

		ELECTRICAL EQUIPMENT	
PROPULSION	PORT	STARBOARD	AUXILIARY EQUIPMENT
a	Generators		l Generators & Governors
b	Exciters		m Motors
c	Air Coolers		n Switchboards & Fittings
d	Motors		o Circuit Breakers
e	Air Coolers		p Cables
f	Control Gear, Cables, etc.		q Insulation Resistance Good
g	Insulation Resistance		r Steering Gear Generators and Motors
h	Insulating Oil Test		s Navigation Light Indicators
i	Overspeed Governors		
j	Magnetic Couplings		
k	Air Gap		

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat.
Spt.

Boiler Securing Arrangements

Main Economisers Exhaust Gas Heated Economisers

Steam Heated Steam Generators Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules? Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)

Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

A General Examination for deferment of Special Survey until August 31, 1960 in accordance with Circular 1959 was held. (See London Letter dated June 20, 1960.)

As no Drydock was available at this time, the survey was carried out afloat.

LEAVE THIS SPACE BLANK

Survey fees Fls. 100.00

Damage fee

Expenses... 5.00

Date when A/c rendered

