

Rpt. 9a.

Port of


Continuation of Report No. dated

on the

" Jaybank " No. 33754

No 3 Cargo Hatchway on the Freeboard Deck is being removed. Two oiltight hatches to new deep tank are being fitted in lieu of same. each 9'-0" square. Coverings $12 \times 3\frac{1}{2} \times 8\frac{1}{2} \times .5\frac{46}{10}$ [These oil tight covers. supported by bulb angles. Two vents are fitted to deep tanks each 6'-9" \times 12" \times 8/20" bracketed to deck, with wooden plugs & canvas covers.

Reefast. Form C 11 (C). 24/1/35-



© 2020

Lloyd's Register
Foundation

002916-002922-0217

Trun

Trun

Expc

bo

Emp