

COPY

name "BRITISH CAPTAIN" Port SKM No. 13871.  
Last survey date 1.10.62.  
s subject to :-

Temporary repairs to fractured Main Engine tie rod between Nos. 5 and 6 cylinders (port side) being specially examined and dealt with as necessary before the end of September, 1962.

BRL: The above item dealt with and the repairs found to continue efficient but the Surveyor recommends a further examination be made before the end of November, 1962 (2 months limit).

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as above as now amended.



© 2020

Lloyd's Register  
Foundation

002938-002946-0166

D  
(MF)