

4E

subject to the bottom shell plate of the boiler being re-examined internally by the end of 8.61.

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

4 - AUG 1961


NAME "ENDCLIFFE" REPORT Cff. No. 61491

Surveyor reports both furnaces of main boiler collapsed, stated to have been caused by over-heating of excessive deposits of scale and river mud. Surveyor recommends that class be made subject to the main boiler not being used until it has been specially examined and repaired as found necessary.

Owners have decided to lay up vessel at Newport and will advise us in due course of their decision as to the future of the vessel.

SRL - This item to be deleted because of recommendation now made.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as now recommended.



2.8.61

© 2020
Lloyd's Register
Foundation

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

002938-002946-0319