

COPY

Ship's name

ST. EVAN

Port

Fal

No.

14319

Class is subject to

NIL

Last survey date

19/9/62

Docking

MBS due 9.62, now partly led

The Surveyors reports star fractures  $1\frac{1}{2}$ " to 2" in length on bottom shell plate of the main boiler radiating from two lower rows of the wing combustion chamber wrapper plate stays. No repairs effected.

The H/E H/P cylinder machined vertically on p.s. 24" long.

The Owners state tug now sold for breaking and the notation "To be broken up" entered against the ship's name in the R.B.



GC/1/2020

Lloyd's Register  
Foundation