

Class is subject to Metalock repairs to aft "Webers" feed pump water end being examined by 1/61 (imposed 2/59) and to repairs to fractures in fabricated "A" frames between starboard outer main engine No. 3 and scavenge pump being specially examined by 3/61 (12 months limit) (imposed 2/59).

Received by Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor ..... 14 NOV 1960

SHIP'S NAME ..... DOMINION MONARCH ..... REPORT ..... Ant. .... No. 36072

CS advanced.

ABS due 1/61, partly held now.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of ABS 10/60 when the survey has been completed as per this report, subject as above.



© 2020  
JN

Lloyd's Register  
10.11.60  
Foundation

002947-002955-0171