

Do. of excess of Hatchways  
Do. above Crown of  
Engine Room ..  
Gross Tonnage

211.52  
22.50

Longitudinal Number ..... 4106.4 -  
Depth "d," at middle of length (See Secs. 2 & 13) .... 11.66 -

Owner, James Langlois  
Managers

250.12.10.

F.E.

Received by Chief Ship Surveyor 5/4/11

Received from Chief Ship Surveyor

VESSEL'S NAME "H. L. Ann Ford McNeill" Rpt. Abu No. 10508

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 35-1

Depth "d" 11.66

Framing: Table No. 3 page 9

Description Single angle, as approved

Longitudinal No. 4106

Proportions Length = 9.0  
Depth =

MAIN Deck Sheerstrake means 10 not required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A-1 ("Stub") "Steam Trawler", as recommended.

$\pm$  100A-1 ("Stub") "Steam Trawler"

1/8" x  
D.T. 5' 11" 1/2  
BK 7 1/2" 3BH. Gen. Lloyd's at 60

© 2020  
Lloyd's Register  
Foundation

002956-002969-0023

Angles on upper edge  
Spacing  
BEAMS, Third and Fourth Deck, Single Angle,  
Bulb Angle, Plate, Tee Bulb, or Channel  
Poop Deck Stringer Plate, breadth & thickness  
Angle on ditto  
Tie Plates