

Breadth 39.2 Draught Moulded Afloat and in drydock

FRAMES DOUBLE BOTTOM AND BEAMS.

58a.10.47.

1 DGW

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME TROCHISCUS

REPORT

Liv.

No. 129751

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."— (Extract from Sub-Committee's Report, 24 / 5 / 92.)

Nature of Survey Docking, Damage.

When due

NOTED

Subject to 30 fathoms of chain cable being verified at the next drydocking.

ENDORSEMENT OF CLASS (B)

Indents in shell plating, etc. (p & s).



2-12-49

C.S.S. Records Dept. to note.

Renewals to rudder plating, also cracks in tank plating.



© 2020

Lloyd's Register

002956-002969-0242

line at toe of frame
Middle Line Keelson, on Floors, Angles,

Spacing

Second Deck, amidships, Angle, [or [