

"JALNA" ex "PEIK"

List of Plans and Certificates forwarded with Kiel Reports No. 609
Kiel Letter No. 474/F. dated 1st July, 1952

1. Kiel Cert. No. 5006 - 1 stern frame boss
2. Photostat copy of Makers' test cert. on 167 m 5" steel wire hawser, 24.9.51
3. Plan No. 3103002 - stern frame boss (approved plan)
4. " " 3109002 - Foundations for Diesel generator aggregate (approved plan)
5. " " 3109001 - Foundation for main engine (approved plan)
6. " " 3000002 - Lengthening - stengthening of sheer strake and str.pl.(appr.pl.)
7. " " 3000003 - " - midship section

8. Kiel Rpt. 10 No. 609 on MAK engines Nos. 14414 and 14415
9. Düsseldorf Rpt. 6, No. 1520 - 1 crankshaft - 3.5.51
10. Düsseldorf Rpt. 6 No. - - 1 crankshaft - 20.7.49
11. Photostat copy Germanischer Lloyd cert. No. 75073 D - 1 air compressor
12. " " " " " 75077 D - 1 air compressor
13. Hamburg Rpt. 7 b on one D.C. generator - Test No. 566,
14. " " " " " " " 565
15. " " 10 on D.C.generator Test No. 565
16. Hans Still works test on D.C. geneator No. 516151
17. Photostat copy Düsseldorf Cert. No. Do.F.542 on 6 flansh shafts, 12.8.51
18. Hamburg Rpt.10 on D.C. generator Test No. 566
19. Hans Still works test on D.C.generator No. 511652
20. Düsseldorf Cert. No. Do.F.542 12.8.51 - 6 flansh shafts (photostat copy)
21. Hansa-Motorenfabrik works test on starting air compressor No. 539505
22. " " " " " " fresh cooling water pump No. 539 592
23. " " " " " " fresh cooling water pump No. 539 591
24. " " " " " " sea cooling water pump No. 539 593
25. " " " " " " sea cooling water pump No. 539 590
26. " " " " " " sea cooling water pump No. 540 266 (aux.)
27. " " " " " " fresh water cooling pump (aux.) No. 540.265
28. " " " " " " L.O. service pump No. 541 177
29. " " " " " " L.O.standby pump No. 539 594
30. " " " " " " hydrofor pump No. 541 182
31. Howaldtswerke Kiel works test on electrical installation 19.5.52
32. MAK works test on engine No. 14414 (Photostat copy)
33. " " " " " " 14415 (Photostat copy)
34. Augsburg Cert. on 1 air compressors Test No. 3126 (photostat copy)
35. Augsburg Cert. on crankshaft and connecting rods - No. 277 (Photostat copy)
36. Augsburg Cert. on 2 vertical centrifugal pumps, Test Nos. 3139/1-2 " "
37. Augsburg Cert. on 2 " " " " 3138/1-2 " "
38. Bremen Cert. on 1 fresh water cooling pump, Test No. 267 " "
39. Bremen " 2 1 sea water cooling pump, Test No. 268 " "
40. Augsburg Cert. on one lub.oil pump, Test No. 3245 " "
41. " " " one " " " Test No. 3152 " "
42. Bremen " " one fresh water cooler, Test No. 265 " "
43. Kiel Cert. No. 435, on one centrifugal pump " "
44. Düsseldorf Cert.No. Df.F. 2701 propeller shaft and nut " "
45. " " " Df.F. 2770 2 intermediate shafts " "
46. Glasgow " " C. 89591 on one ~~bronze~~ manganese bronze propeller " "
47. Hamburg Cert. " 44823 on one cast iron propeller. " "



© 2020

Lloyd's Register
Foundation

002970-002977-0194

ACCOUNTS *W. H. H.*

CLASSIFICATION

Hx
pl
admiral
SM



© 2020

Lloyd's Register
Foundation

If so, is the Report sent now, or when will it be sent?

no in damage
offer

REPAIRS,

Damage

1) Col

2) unk

NOW DO

REPAIR

Dem

SUMMARY C

Renew

Renov

Faired

PRESENT CO
Decks

Caulking of I

Coatings

Paints & Res

Outside Plating

" "

Frames

Reverse Fram

Longitudinal

Transverse

Floors

Keelsons

Stringers

Inner Bottom

are the Ta

are the Ta

ENER

this s
surve

his s

he re

-weld

Survey Fee

Wear

Special Dam

Strut

Traveling E

Gunday

late fe

transfer Ink. (MADE
requested not to write o

Cell/Bor
total cap
On
N.B.

Last 1

Periodical Sa
the Survey
and subse
other caus
replaceme
State also