

5m,9,35.

1

fees paid

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Twin Screw "CLAN CAMERON" Report Grk. No. 20312

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey FIRST ENTRY When due --

*100A1 "With freeboard"

2 Dks. & Shelter Dk.

Cell. DB 393' 1266t, MT 39' 1360t, FPT 68t, APT 126t.

FK, Duct keel forward of machinery space, 7 BH (Coll. BH to Shelter dk 6 BH to 2nd Dk.), pt. Cem., Lloyd's A & CP.

P 31' B 99' F 69'



© 2020

Lloyd's Register
Foundation

002978-002988-0055