

POLSKI REJESTR STATKÓW

s.s. THORNBURY

PHOTOGRAPHIC RECORDS OF DAMAGE TO FORE-PEAK AND No 1 D.B. TANK

1. Before commencement of repairs- wooden plugs, cracked stem bar and cracks of plates clearly visible

XXX

2. Closed-up view of cut frames

XXX

3. Part of shell plating removed, damaged ends of frames cut off.

XXX

4. Repairs completed

XXX




© 2021

Lloyd's Register
Foundation

003023-003028-0039 1/5

POLSKI REJESTR STATKÓW



- 1 -



© 2021

Lloyd's Register
Foundation

0039 2/5

POLSKI REJESTR STATKÓW

POLSKI REJESTR STATKÓW
PLACÓWKA Nr 2 w GDAŃSKU

- 1 -



© 2021

Lloyd's Register
Foundation

0039 2/5

POLSKI REJESTR STATKÓW



- 2 -



© 2021

Lloyd's Register
Foundation

0039 3/5

POLSKI REJESTR STATKÓW

2

CLOSED-UP VIEW OF
CUT FRAMES

POLSKI REJESTR STATKÓW
PLACÓWKA Nr 2 w GDAŃSKU

- 2 -



© 2021

Lloyd's Register
Foundation

0039 3/5

POLSKI REJESTR STATKÓW



- 3 -



© 2021

Lloyd's Register
Foundation

0039 4/5

POLSKI REJESTR STATKÓW

3

PART OF SHELL PLATING REMOVED
DAMAGED ENDS OF FRAMES CUT OFF

POLSKI REJESTR STATKÓW
PLACÓWKA Nr 2 w GDAŃSKU

- 3 -




© 2021

Lloyd's Register
Foundation

0039 4/5

POLSKI REJESTR STATKÓW



- 4 -



© 2021

Lloyd's Register
Foundation

0039 5/5