

Class is subject to

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME SS. CAPE DREPANON REPORT Dublin No. 9070.

ES. due 11/57, now partly held.

TSEL. due 1/60.

SPS. due 6/56

MBS. due 7/58.

Now held.

Docking Repairs.(The ship has the addition of
"Surveys overdue 11/59".)Some repairs and renewals made
to main and auxiliary machinery and boilers.It is submitted that the
vessel **WILL BE** eligible
for the record MBS. 1/61, SPS 10/60, TSEL. 11/60 NOW. at ES. 1/61
when the survey has been
completed.

To complete the ES. examine:-

Boiler oil fuel heaters (2)

Boiler feed-water heaters.

Fire extinguishing arrangements

The Surveyors

all these
itemsAssign
ES 1/61EXAMINED
(Dublin) 2/2/61

6/2/61

31 JAN 1961

SS. 'CAPE DREPANON'

Dublin 907

Before this case receives consideration, the
Surveyors should be asked to state whether
the boiler oil fuel heaters (2) and feedwater heaters
and the fire extinguishing arrangements were examined
it would appear from the report that there have not been done
a record of ES. 1/61 has recommended not.
W.T.

30/1/61

Sgt. overleaf

All above
items exam'd

(Dublin ltr 2/2/61)

R



© 2021

Lloyd's Register
Foundation

Surv
Reg
Cor
to
(1)
(2)
(3)
(4)
(5)
(6)
(7)
and
Ship
me
Rec
rec
SS.