

REPORT of SURVEY for REPAIRS, &c.

ing report 12-12-57 When handed in at Local Office 12-12-57 Port of BOMBAY
 Survey held at BOMBAY Date, First Survey 28-10-57 Last Survey 8-12-1957
 (No. of Visits 5)

on the ~~Wood, Iron or Steel~~ S.S. "EASEDALE"
 Built at Haverton Hill By Whom Furness S.B.Co.Ltd When 1942 - MONTH 2

UNAGE: 8032 Owners The Admiralty Owners' Address
 (If not already recorded in Appendix to Register Book).

R DK. 4667 Managers Port belonging to

d Afloat or in Dry Dock? Name of Dock Ritchie Dry Dock Destined Voyage

ell D Bor D Ba feet; uE&B feet; f feet
 capacity tons. FPT tons; APT tons; MT feet tons

All alterations in the existing records should be underlined.
 The Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined.
 the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating
 in the boiler space.

Report, No. 11669 Port S.W.C.

Surveys, when held must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs,
 and, in detail the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of
 must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report,
 summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should
 be stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this

Where the Surveyor has not made a special damage report he is required to state whether he offered

for this purpose and to whom and why they were declined Society's Freeboard (if assigned) as

Was a damage report made by anyone else? If so, by whom? painted on Ship and now verified

OR EXAMINATION AS PER RULE, FOR

vessel placed in dry dock. Undocked 9-12-57.

om and rudder cleaned, examined and recoated.

n cables ranged in the dock cleaned, examined and replaced on board.

, casings, coamings, tank lids, hatchways, skylights, doors and closing appliances,

gear and windlass examined.

Annual freeboard survey carried out at this time.

now done (Wear & Tear)

pproximately 4000 rivets renewed in the sheer strake plating spread over centre 2/3rds of

S. (Slack and leaking).

he rudder lifted and the top and bottom gudgeon rebushed. Rudder ford. facing plate

AGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Paired or Repaired ..								
aired in place ..								

ON OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Good	No	✓	(State if on Felt.)
Good	State if Tanks now tested	✓	When put on, Month Year
Good	Bulkheads	Good	Boats
Good	Ceiling	✓	Masts, Yards, &c.
Good	Cement or Asphalt (State which.)	✓	Condition, how ascertained
✓	Rudder	Good	(State if wedges removed)
✓	Steering gear and its connections	Good	Sails
✓	Windlass	Good	Equipment letter
✓	Have pumps now been examined and found efficient?	✓	Anchors, No. of
✓	Have Sluice Valves now been examined and found efficient?	✓	Chain Locker
✓	Have Watertight Doors now been examined and found efficient?	✓	Cables (State if now ranged)
✓	Have Ventilators and their Coamings been examined and found efficient?	✓	Cables length mean diamr (on board)
✓		✓	Cables Rule length size
✓		✓	Hawser & Warps
✓		✓	Standing and Running Rigging

Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example -
 to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of
 survey, 1,24, and the notations of ss. No. 1-24 and pmd 24, &c."

The above vessel is eligible in my opinion to remain as classed with fresh record of docking

y 12-57.

Cond. Rs. 215/-
 (Per Section 29) A.L.L. Rs. 585/-
 Special Damage or Repair Fee (if any) Rs. 150/-
 (Per Sec. 29) Rs. 40/-
 Surveying Expenses (if chargeable) Sp.Att. 8/12/57 Rs. 100/-
 Surveyor's Fee, if any

Committee's Minute

Character Assigned DS 12, 57

Note: water Bom MBS 12, 57 (with endorsement (m))

the Times of India Press, Bombay.

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

003075-003082-0193

Lloyd's Register
Foundation