

Do. of excess  
Do. above Cr  
Engine Ro  
Gross Ton  
Less Crew S

2m. 8.15.

1

"~~Jacob~~ J. LUCKENBACH  
DJAKARTA-RAYAX

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "SOUTH BEND". Report Phl. No. 3140

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 245893.)

Nature of Survey

When due

The downtown pump has been dispensed with as a War  
Emergency Measure.

The class of this vessel is subject to a bolt through shell  
and margin angle at starboard fore end of engine room being replaced  
by a rivet at the next dry docking.

100 A.L. (Steel) Shelter Dk. with freeboard. } subject to  
2 Dks. (Steel) and Shelter Dk. (Steel). }

Cell DB 389' 183lt. Tween dk. tanks in E & B space 36' 405t.

FPT 281t. APT 271t.

FK. 10 BH to Shelter Dk. pt. Asp. A. & C.P.

See Bal. Report No. 3395 (Feb. 1923)  
2 Bulk<sup>hds</sup> dispensed with

M  
15. 4. 19.



© 2020

Lloyd's Register  
Foundation

003124-003130-0158

BEAMS, Po

A

S