

Received from Chief Ship Surveyor

7 OCT 1959

S NAME "NICANIA" REPORT H.Kg. No. 14961

VC

anding Conditions of Class: NONE

— Appendix. (As before on ~~XXXXXX~~)

e of Present Survey: (Afloat and in dry dock)

Docking; Wear and tear and temporary repairs.

Recommendation:

SUBMITTED record of 'DS. 6.59' be assigned as recommended, SUBJECT to deck plating (temporarily doubled) being specially examined and dealt with by the S.S.

DS. 6.59. SUBJECT.

IN S.R.L. APPENDIX.

Keel plate No.3 set up.

Port bilge keel buckled.

Indents in shell plates (p & s)

Shell plate F.4 (p.s.f.) fractured and E.W.

The Hong Kong Surveyors have forwarded a Rpt.8 (Dr.) at this time stating the shell and deck plating recommended to be dealt with by the S.S. Surveyor's recommendation

concerned in. *fdw*

003162-003176-021