

28 JAN 1958

No. 625.

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 20th. Oct. 1957. When handed in at Local Office 1957.

Port of South Georgia.

No. in
Reg. Book.

Survey held at Leith Harbour, S.Ge.

Date, First Survey

22.9.57

Last Survey

14.10. 19 57.

28019

on the ~~Woolly~~ ~~Iron~~ Steel

S/W "SOUTHERN STAR"

TONNAGE :-

GROSS 340

UNDER DK.

NET 121

Built at Middlesbrough

By whom

Smiths Dock Co. Ltd.

When

1930

MONTH

8

Owners The South Georgia Co. Ltd.

Owners' Address

(If not already recorded in Appendix to Register Book).

Managers Chr. Salvesen & Co.

Port belonging to Leith

Surveyed Afloat or in Dry Dock? Drydock Name of Dock Strömness

Destined Voyage Whaling Purposes

Cell DBor DBa

feet; uE & B

feet; f

fe

total capacity tons. FPT

tons; APT

tons; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Report, No. 585 Port Leith Harbour, S.Ge.

Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete repairs should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to wear; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the cause of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. Dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he has made a special damage report for this purpose and to whom and why they were declined N.A.

N.A.

Was a damage report made by anyone else? if so, by whom? N.A.

EXAMINATION AS PER RULE, FOR Annual Survey.

Ship was placed on blocks in Strömness Floating Dock on 22nd. September 1957, when the hull, general equipments were examined and the following repairs recommended to be made.

Indent in forepeak to be faired and 23 rivets to be renewed.

Welding opening cover on casing to be repaired.

Air ventilator to engine room to be renewed.

Funnel to be renewed 12 ft. from top.

Hull to be scraped and coated.

Ship was again examined prior to undocking on 14th. October 1957, when it was found that the repairs recommended above had been carried out in a satisfactory manner. Also some minor deck repairs were effected.

DAMAGE REPAIRS :-

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

and Faired or Repaired

Repaired in place

CONDITION OF THE

Good Order

In Good Order

Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

In Good Order

Bulkheads In Good Order

Celling N.A.

Cement or Asphalt In Good Order

Rudder In Good Order

Steering gear and its connections I.G.O.

Windlass N.A.

Have pumps been examined and found efficient? Yes

Have Sluice Valves been examined and found efficient? Yes

Have Watertight Doors been examined and found efficient? N.A.

Have Ventilators and their Coamings been examined and found efficient? Yes

Air and Sounding Pipes In Good Order

Doubling Plates under Sounding Pipes I.G.O.

Engine Room Skylights In Good Order

Coal Bunkers, Openings, Covers, &c. N.A.

Oil Bunkers In Good Order

Scuppers In Good Order

Cargo Hatchways In Good Order

Hatches In Good Order

Planking

Caulking

Treenails

Breasthooks & Stemson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

State if examined

Copper, or Y.M.

(State if on Felt.)

When fitted, Month

Year

Boats In Good Order

Masts, Yards, &c. In Good Order

Condition, how ascertained Examined

(State if wedges removed.)

Equipment letter C.

Anchors, No. of 3

Cables (State if now ranged) No

" length 180 mean diam. 1.1/8"

(on board.)

" Rule length size

Chain Locker In Good Order

Hawsers & Warps In Good Order

Standing and Running Rigging I.G.O.

Sails N.A.

Observations, Opinion as to Class, Recommendation, &c.:

Clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38."

The vessel, as far as now seen, is in good and efficient condition and eligible in my opinion to remain as classed with fresh record of Docking Survey 10.57.

on 23) Annual £ 10 : 10 : 0

Pair Fee (if any) £

Chargeable) £

(if any) £

miles

Assigned

for

Assessed

D5 10.57

TS 10.57

(With Endorsement)

MBS 10.57

Fees applied for,

19

Received by me,

19

THURSDAY 13 FEB 1958

Acting Surveyor to Lloyd's Agent.

THURSDAY 28 JAN 1960

Delete "LUSO 8.58"

+ insert

"Surveys overdue 8.58"

Lloyd's Register Foundation

A semicircular M.S. Flange $\frac{1}{2}$ " thick was made and fitted with new bolts on the upper half of the stern tube flange through the bulkhead. Further the fractured piece of the stern tube were also bolted to the M.S. Flange.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.



© 2020

Lloyd's Register
Foundation