

Received from Chief Ship Surveyor..... 24 JAN 1962

NAME "SUERTE" REPORT s (a) Lon. No. 146242  
(b) Hul. 56401

Standing Conditions of Class: SUBJECT to indented keel and bottom and side shell plating etc. being examined and dealt with as necessary at the next drydocking and to Nos. 3 & 5 holds and 'tween decks (fire dam.) being examined and dealt with as necessary by the Special Survey.

Appendix. (As before ~~xxx None~~)

Scope of Present Survey: (Afloat ~~and in dry dock~~)

- (a) Temporary repairs on account of collision damage.
- (b) Further examination of above.


Recommendation:

SUBJECT as above, and to set in soft nose stem plate and shell plate in 2nd strake below sheer (s.s.) in way of No.1 hold being examined and dealt with as necessary by the Special Survey.

As Now. Subject

~~IN S.R.L. APPENDIX.~~

~~Inner bottom plating in Nos. 2,4 & 5 holds wavy.~~



© 2020  
W.O. 1  
23/1/62.

Lloyd's Register  
Foundation