

January 6, 1939.

S.S. "WALTER B. REYNOLDS"

It is noted that the hatch beams have been reinforced to Rule standard.

Closing arrangements for ventilators to be supplied where necessary.

Closing arrangements for air pipes to be supplied where necessary.



© 2020

Lloyd's Register
Foundation

003245-003251-0185