

4E

15 JUL 1959

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME..... KING WILLIAM

REPORT Cbo

No. 4433

The Surveyor reports some repairs effected to
 the steering gear electric motor but states that
 the present position is that no electrical spare
 parts for this type of motor are aboard the vessel
 and recommends that the class be made subject to the
 spare armature shaft with half coupling and one spare
 field coil being placed on board at the first opportunity.
 The Surveyor should be informed that the class cannot be
 made subject to the spare machinery parts being on
 board the vessel.

IT IS SUBMITTED this vessel is eligible to
 remain as classed.



© 2020

14.7.59

Lloyd's Register
 Foundation

003075-003281-0081