

"EMPIRE MIRANDA"

Rpt. Grk. No. 22309

Before this case receives the consideration of the Committee the Surveyors should be requested to state whether the spacing of the rivets in the treble riveted butts of the bottom plating is $3\frac{1}{8}$ " instead of $3\frac{1}{2}$ " as reported ^{and} whether the scantlings of the divisional watertight bulkheads ^{in the tween decks} and the face bars of the upper deck transverse are as reported or in accordance with the approved bulkhead and profile and deck plans respectively.

They should also be requested to furnish the breadth of the upper deck stringer plate and the scantlings of main bulkhead No. 85 which have been omitted from their report.



© 1920 *J.C.D. G.M.B.*
18.5.43.

Lloyd's Register
Foundation

003299 - 003304 - 0275