

yes

003409-003416-0214

Parknasilla.

Abn. 17182.

It is submitted the Surveyors
 be requested to state whether the amperages
 & lengths of conductors on the accommodation
 & deck circuit & the navigation circuit
 are correctly reported as it appears
 from the figures that there is an
 excessive drop in pressure in these
 circuits.

Ln 16/11/32

J.C.

R.A.

S.M. 15/7/32

Monte Lee reply 18/11/32

yes

accessibility of all parts

yes

absence of fuses on back of board

yes