

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME

"ANTAR"

Rpt.

Sld

No. 33044

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15582

Depth "d" -

2nd Long. No. 39254

Proportions =  $\frac{L}{D}$  11.08

Framing Bulb angle framing as approved. Sheerstrake As approved.

D to Shelter dk 38'. D to 2nd dk 29'. D for scantlings 37' (i.e. to 8' above 2nd dk).

Owners' extras include:- Increased 'tween deck frames, sheerstrake and shelter deck plating.

This is a complete superstructure vessel with a tonnage opening and similar to the "PUTNEY HILL", "DUKE OF ATHENS" etc. The tank top plating under the hatchways has been increased in thickness in lieu of ceiling.

This vessel appears to have been built in accordance with the

Rules and the approved plans, and it is submitted she is eligible to

be classed **100A1** "With freeboard"

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk and Shelter dk

Cell DB 356' 1179t, MT 29' 1205t, FPT 134t, APT 155t.

FK, 7BH (Coll to Shelter dk, 6 to 2nd dk); Lloyd's A & CP

O.L. 442.9'

E.S.D

at  
2"

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L:

(1 bower anchor and 45 fathoms of chain cable to be supplied).



Lloyd's Register  
Foundation

003421-003428-0181