

16 JAN 1963

Ship's name "JOHORE BAHRU" Port Chg No. 314

Class is subject to fractured shell plate G.9(s.s. from aft) being specially examined and dealt with as necessary next drydocking to keel plate No.14 and A.15 (p.s. from aft) being specially examined and dealt with as necessary by the S.S. also to 150 fms. of chain cable being renewed at the earliest opportunity.

ACTION is DEFERRED for S.S. by 7,63 and for S.R.L. Appendix (as before ~~xxxxxxx~~) a short time for Equipment.

Surveys due SPECIAL SURVEY (C) due 7,62. Postponement until 7,63 approved 12.10.62 following a satisfactory G.E.

Nature of present survey (afloat ~~and in drydock~~)

Temporary repairs to wasted shell plates F.8 & G.8 (p.s.) in way of E.R. Bulkhead.

Is interim certificate in order

Yes/~~No~~

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation

SUBJECT as above, and to fractured shell plates F.8 & G.8 (p.s.f) being dealt with as necessary by 6,63 also to shell plate G.10 (s.s.a) being specially examined and dealt with as necessary next drydocking, but further ACTION continue to be DEFERRED for S.S. by 7,63 and for a short time for Equipment.

SUBJECT

IN S.R.L. APPENDIX.

Indents in shell plates (p & s).

© 2020
15/1/63

See Ut to H Rg 2/1/63 re supply of equipment

Lloyd's Register
Foundation

003434-003443-0024