

Sp. Light Hole
Shell Test Hole.

S. 61. 1st 40

62. " 35

15.2 " 25

F 11 " 34

F 12 " 30

E 5 " 20

E 13 " 30

E 14 " 35

P. 61. 40

P. 62. 35

P. D. 2. 34

P. D. 3. 30

Additional Test Holes Cont.

S. A 2 40

S. B 5 33

S. B 9 — ?

S. C 4 40

S. C 6 45

S. C 7 30

S. G 14 30

S. F 16 25

S. G 16 44

P. E 5 25

P. E 13 42

P. F 11 50

P. F 12 50

P. B 2 24

P. A 2 36

P. F 16 33

P. G 16 36



Lancashire Repairs to Net-in Shell (p.s.f.); to indented main Sheerstrake
 plt. N°3 (s.s.f) - to buckled floors in way of Bottom
 Shell plt. A6 (p.s) to be effected at the next SS (due 23rd)

In the above are PD2,3,4; E3,4,5; F2,3 with fis in way; & SF3.

Cat. B - Port A3,5,6,7,8,9

B2,3,4,5,6,7,8

D5 E2 F4,6,7, G 6,7,8,9

Starb B3,4,5,6,7,8

D2,3.

6 (121-6"
 21-6"



© 2020

Lloyd's Register
 Foundation