

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

16 JUL 1959

NAME..... KYLOE


REPORT.....

Sld.

No. 37174

The Surveyor reports examination of intermediate shafting and thrust shaft on account of possible damage due to the vessel laying in alleged foul berth. The alignment of the shafting partially checked but repairs not completed, and the Surveyor recommends that the class be made subject to the alignment of the main engine crankshaft and intermediate shafting being dealt with as necessary before the vessel goes into service.

IT IS SUBMITTED this vessel is eligible to remain as classed subject as recommended.



15.7.59



© 2020

Lloyd's Register
Foundation

003434-003443-0338