

4E
11 SEP 1959

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME.....HYALINA

REPORT

Rot

No. 47784


Docking.

The Surveyor reports examination of sea connections and recommends the class be made subject to the main high inlet valve, the overboard discharge of the main condenser portside, and both port and starboard overboard discharges of the auxiliary condenser being renewed, and the propeller re-examined, before the vessel is re-commissioned.

IT IS SUBMITTED this vessel is eligible to remain as classed subject as recommended.

NB. The Surveyor should be requested to state the nature of the defects relative to the sea connections.

See Rot. h. 10/9/59



1.9.59



© 2020

Lloyd's Register
Foundation

003479-003486-0187

003479-003486-0188