

EA

30 JAN 1963

Ship's name "NORTH POINT" Port H.Kg No. 17330

There is an S.R.L. Appendix item.

The HONG KONG Surveyors report (10,62) this ship examined in dry dock on account of damage stated caused by grounding. Bottom and side shell plating found to be extensively damaged and recommendations have been made for permanent repairs.

Temporary repairs effected at this time prior to ship being undocked pending decision from the Owners regarding ship's future.

On account of extent of the damages now found the Owners have advised the Surveyors the ship has been sold for breaking up purposes.

The above information has already been made known to the Committee and minute of "To be Broken Up" has been inserted in the Register Book. — 7/12/62

In view of the above, SUBMITTED no further ACTION need be taken meantime, pending receipt of definite information as to the ship's ultimate disposal.

S.P.K.
30/1/63



© 2020

Lloyd's Register
Foundation

003525-003532-0061